

Guide Contents
Troubleshooting Cisco IOS Voice Overview
Debug Command Output on Cisco IOS Voice Gateways
Filtering Troubleshooting Output
Cisco VoIP Internal Error Codes
Troubleshooting Cisco IOS Voice Telephony
Troubleshooting Cisco IOS Voice Protocols
Troubleshooting Cisco IOS Telephony Applications
Monitoring the Cisco IOS Voice Network
Cause Codes and Debug Values

Contents

- [1 Troubleshooting T.38 Fax Relay](#)
- [2 Identifying and Isolating the Problem](#)
- [3 Checking Basic Connectivity](#)
 - ◆ [3.1 Normal Voice Connectivity Problems](#)
 - ◆ [3.2 Configuration Problems Related to Dial Peers](#)
 - ◇ [3.2.1 Wrong Dial Peer Being Matched](#)
 - [3.2.1.1 debug voip ccapi inout-Originating Gateway](#)
 - [3.2.1.2 debug voip ccapi inout-Terminating Gateway](#)
 - [3.2.1.3 debug voip ccapi inout-Relaying Gateway](#)
 - ◇ [3.2.2 Incorrectly Configured Dial Peers on One or Both Sides](#)
 - ◆ [3.3 Other Basic Connectivity Problems Not Relating to Dial Peers](#)
 - ◆ [3.4 Fax Connectivity Problems Across the PSTN](#)
- [4 Checking for Slips and Other Errors on Digital Interfaces](#)
 - ◆ [4.1 show controller T1\(E1\) 1/0 Command](#)
- [5 Checking Fax Interface Type](#)
- [6 Ensuring That the Fax Codec is Loaded During the Fax Call](#)
- [7 Disabling Fax Relay and Change Codec for Pass-Through](#)
- [8 Checking for Packet Loss on the Voice Network](#)
- [9 Disabling Fax Relay ECM \(Cisco Proprietary VoIP Only\)](#)
- [10 Enabling T.38 Packet Redundancy \(T.38 VoIP Only\)](#)
- [11 Setting the Fax NSF Command to All Zeroes](#)
- [12 Achieving the Final Stages of Resolution](#)
- [13 Debugging Fax Relay](#)
 - ◆ [13.1 T.30 Messages](#)
 - ◇ [13.1.1 Figure: T.30 Transactions](#)
 - ◆ [13.2 Fax Relay Debug Commands](#)
 - ◇ [13.2.1 debug fax relay t30 all](#)
 - [13.2.1.1 Figure: DSP Message Flow](#)
 - ◇ [13.2.2 debug vtsp all](#)
 - ◇ [13.2.3 debug vtsp vofr subframe 3](#)
 - ◇ [13.2.4 Additional Debug Commands](#)
 - ◆ [13.3 Fax Analyzers](#)
 - ◇ [13.3.1 Figure: Test Equipment Placement](#)

Troubleshooting T.38 Fax Relay

To troubleshoot T.38 fax relay, perform the following steps:

- Make sure that you can make a voice call.
- Make sure that the desired fax protocol was set using the **fax protocol** command on both the originating and terminating gateways.
- Make sure that the fax protocol is configured as T.38 at the global configuration level or at the dial-peer configuration level for both the originating and terminating gateways.
- Use the **show call active {voice | fax}** command to display information for the active call table.
- Use the **show dial-peer voice** command to display configuration information for dial peers.
- For H.323 gateways, use the **debug cch323 all** command to enable all H.323 debugging capabilities, or use one of the following commands to debug problems while making the call:
 - ◆ **debug cch323 error**
 - ◆ **debug cch323 h225**
 - ◆ **debug cch323 h245**
 - ◆ **debug cch323 RAS**
 - ◆ **debug cch323 session**
 - ◆ **debug voip ccapi inout**
 - ◆ **debug vtsp session**
- For SIP gateways, use the **debug ccsip all** command to enable all SIP debugging capabilities, or use one of the following SIP debug commands:
 - ◆ **debug ccsip calls**
 - ◆ **debug ccsip error**
 - ◆ **debug ccsip events**
 - ◆ **debug ccsip info**
 - ◆ **debug ccsip media**
 - ◆ **debug ccsip messages**
 - ◆ **debug ccsip states**

Identifying and Isolating the Problem

The first step to take when you troubleshoot any fax relay issue is to reduce the problem to its simplest form. Many issues arise in situations where multiple fax machines are not able to pass fax traffic. It is easiest to isolate two fax machines that are having problems and concentrate on a simple topology. Determine how these machines are connected to one another and resolve the issue between this pair first. In addition, you should draw a complete picture of the topology and determine how the fax machines are interconnected.

Troubleshooting one issue at a time minimizes confusion and allows for methodical troubleshooting. It is also possible that the solution for this problem resolves other fax relay problems in the network. Most fax relay problems result from poor voice configuration or network design. These lead to basic connectivity problems and physical line or packet loss and jitter problems.

After you have identified and isolated the problem, you need to verify the basic voice configuration and monitor the health of the network.

Checking Basic Connectivity

Basic fax connectivity issues can be the result of the following factors:

- Normal Voice Connectivity Problems
- Configuration Problems Related to Dial Peers

- Other Basic Connectivity Problems Not Relating to Dial Peers
- Fax Connectivity Problems Across the PSTN

Normal Voice Connectivity Problems

Confirm that normal voice calls can be completed before investigating fax connectivity. If there is no telephone attached, unplug the fax machine and connect a regular telephone. If normal voice calls do not connect, the issue might be network-related and you should troubleshoot the problem as a normal voice connectivity issue before proceeding with fax troubleshooting.


Configuration Problems Related to Dial Peers


Some configuration problems are associated with dial peers, for example:

- Wrong Dial Peer Being Matched
- Incorrectly Configured Dial Peers on One or Both Sides

Wrong Dial Peer Being Matched

After ensuring that voice calls can be successfully completed in both directions through the voice network, issue the **show call active voice brief** command and note the dial peers that are being matched with each voice call.

 **Note:** When you have VoIP trunks, you should be able to see all the call legs with the **show call active voice brief** command. In some versions of Cisco IOS Software Release 12.2, there is a bug in the **show call active** command. As a result, a fax call that comes through a VoIP trunk no longer appears. When you issue a **show call active fax brief** command, the call is listed. For more information about this bug, see Cisco bug IDs CSCdx50212 and CSCdv02561 (registered customers only).

 **Note:** Ensure that the configured dial peer is the peer that is being matched.

In the command output shown below, you can see that the outbound VoIP call leg is using peer ID 100.

```
Router# show call active voice brief

Total call-legs: 2
1218 : 51710253hs.1 +415 pid:400 Answer 400 active
dur 00:01:08 tx:3411/68220 rx:3410/68200
Tele 3/0/0:43: TX:68200/6820/0ms g729r8 noise:0 acom:2
i/0:-51/-44 dBm
1218 : 51710396hs.1 +272 pid:100 Originate 100 active
dur 00:01:09 TX:3466/69320 rx:3467/69340
IP 2.1.1.2:17092 rtt:56ms pl:64730/0ms lost:0/1/0
delay:69/69/70ms
g729r8
Total call-legs: 2
```

A common cause of fax relay problems is that the correctly configured dial peer is not the one being matched. It is also common that there is no particular incoming VoIP dial peer configured on the terminating gateway, and Cisco IOS Software selects the first appropriate (including default) VoIP dial peer as the incoming dial peer. Hence the parameters for this incoming dial peer might not match those of the outbound dial peer on the originating gateway.

It is not always necessary to have identical configurations on the outgoing and incoming VoIP dial peers. When you have a fax relay problem, though, make sure you have a dedicated incoming VoIP dial peer on the terminating router and that its configuration matches the configuration of the outgoing VoIP dial peer on the

Cisco_IOS_Voice_Troubleshooting_and_Monitoring_--_Fax_Relay

originating router. The following configuration for ISDN-connected routers is an example of specific, matching VoIP dial peers for the destination pattern "5..." outbound on the originating gateway and inbound on the terminating gateway.

Originating Gateway	Terminating Gateway
Incoming POTS peer: Dial-peer voice 1 pots Incoming called number. Direct-inward-dial Port 1/0:15	Outgoing POTS peer Dial-peer voice 10 pots Destination-pattern 5... No digit-strip Port 2/0:15
Outgoing VoIP peer: Dial-peer voice 2 voip Destination-pattern 5... Session target ipv4:1.1.1.1 Fax rate 144400 fax protocol t38 ls-redundancy 0 hs-redundancy 0	Incoming VoIP peer: Dial-peer voice 20 voip Incoming called-number 5... Fax rate 14400 fax protocol t38 Ls-redundancy 0 Hs-redundancy 0

You can also check dial-peer matching by issuing the **debug voip ccapi inout** command. The debug output from this command (as shown below) includes an ssaSetupPeer message that lists all the dial-peers matching the called number. A ccCallSetupRequest message follows with the outbound peer option indicating the outgoing VoIP dial peer selected. When multiple VoIP dial peers are configured for the same destination, it is possible that the initial call setup could fail and another dial peer could be tried. In this case, another ccCallSetupRequest appears in the debug.

debug voip ccapi inout-Originating Gateway

```
ms-3640-13b# show call active voice brief

Total call-legs: 2
1218 : 51710253hs.1 +415 pid:400 Answer 400 active
dur 00:01:08 tx:3411/68220 rx:3410/68200
Tele 3/0/0:43: TX:68200/6820/0ms g729r8 noise:0 acom:2
i/0:-51/-44 dBm
1218 : 51710396hs.1 +272 pid:100 Originate 100 active
dur 00:01:09 TX:3466/69320 rx:3467/69340
IP 2.1.1.2:17092 rtt:56ms pl:64730/0ms lost:0/1/0
delay:69/69/70ms
g729r8
Total call-legs: 2
```

debug voip ccapi inout -Originating Gateway

```
.Jun 4 21:06:43.461: ssaSetupPeer cid(19)
peer list: tag(400) called number (5074)

.Jun 4 21:06:43.461: ccCallSetupRequest
(Inbound call = 0x13, outbound peer =100,
dest=, params=0x62F1CC70 mode=0, *callID=0x62F1CFD8,
prog_ind = 0)
```

On the terminating voice gateway, the first line of the **debug voip ccapi inout** call trace (as shown below) is a '**cc_api_call_setup_ind**' message with a **peer_tag** option that refers to the incoming VoIP dial peer on the

terminating gateway.

debug voip ccapi inout-Terminating Gateway

```
.Jun 4 21:06:43.461: cc_API_call_setup_ind
(vdbPtr=0x62F07650,
callInfo={called=5074,called_oct3=0x80,
calling=5075, calling_oct3=0x0,>calling_oct3a=0x83,
calling_xlated=false,
subscriber_type_str=Unknown,fdest=1,
peer_tag=400, prog_ind=0},callID=0x635F72D0)
```

Incorrectly Configured Dial Peers on One or Both Sides

After you confirm that the correct dial peer is being matched (in this case dial-peer 100 for the originating gateway and dial peer 400 for the terminating router), confirm in the configuration that the dial peer is configured correctly for fax. Here are some common errors to check for on both sides of the call:

- Fax relay is disabled (that is, the **fax rate disable** command has been issued on the dial peer) while a low bandwidth codec has been in use.
- The dial peer on one voice gateway is configured for Cisco fax relay but the other voice gateway is a Cisco AS5350/AS5400. Cisco AS5350/AS5400 universal gateways support only T.38 so the negotiation fails.
- The default dial peer is being used inbound on the terminating gateway, and default parameters do not match those for the outbound dial peer on the originating gateway.
- Incorrect compand type.

The companding type for the US is μ -law, for Europe and Asia it is a-law. You can issue the **show voice call** command to see which value is currently configured. If you are on a BRI or E1 port, the companding type on the router does not match the one on the connected device, and calls sometimes fail and sometimes connect, but the voice becomes heavily distorted so that the person becomes unrecognizable and a high low-pitch noise level appears.

In Cisco IOS Release 12.2(3) the **compand-type** command is missing on the BRI ports, leaving the companding type to the default value. For more information about this bug, see Cisco bug IDs CSCdv00152 and CSCdv01861 (registered customers only).

Other Basic Connectivity Problems Not Relating to Dial Peers

Here are some basic connectivity issues that are related to dial peers:

- Cisco IOS software incompatibilities on gateway pairs. It is not always required that Cisco IOS software releases match, but you should check releases when problems occur.
- Compressed Real-Time Transport Protocol (cRTP) has several known problems. Fixes are available for these problems and it makes sense to disable cRTP when problems occur. You can then decide whether a Cisco IOS software upgrade is an appropriate course of action.
- On Cisco AS5300 voice gateways, ensure that the VCWare and Cisco IOS software are compatible.

Fax Connectivity Problems Across the PSTN

If voice calls work in both directions but fax calls are failing in at least one direction, check that normal faxing between these two machines works across the PSTN. In other words, ensure that the fax machines successfully transmit faxes to each other using the PSTN without traversing the VoX network. If they do not, the fax machines may have problems that need to be addressed before you consider fax relay problems.

debug voip ccapi inout -Originating Gateway

Checking for Slips and Other Errors on Digital Interfaces

If there are any T1 or E1 digital connections used by the routers performing fax relay, make sure that they are error free. Fax relay is very sensitive to errors on digital interfaces, especially slips. The errors may not be noticeable on voice calls but they can cause faxes to fail.

show controller T1(E1) 1/0 Command

```
Router# show contr t1 1/0
T1 1/0 is up.
Applique type is Channelized T1
Cablelength is long gain36 0db
No alarms detected.
alarm-trigger is not set
Version info Firmware: 20010805, FPGA: 15
Framing is ESF, Line Code is B8ZS, Clock Source is Line.
Data in current interval (132 seconds elapsed):
0 Line Code Violations, 0 Path Code Violations
0 Slip Secs, 0 Fr Loss Secs, 0 Line Err Secs,
0 Degraded Mins
0 Errored Secs, 0 Bursty Err Secs, 0 Severely Err Secs,
0 Unavail Secs
```

The T1 or E1 controllers at both originating and terminating gateways should be error free, as shown above. If errors occur, repeat the **show controller** command several times during the call to see if the number of errors increases. The most common problem of slips is a synchronization problem resulting in clocking errors.

In packet voice networks, confirming that the router is clocking from the line is usually sufficient. If it is not, ensure the **clock source line** command is entered at the controller level. However, in VoATM or TDM networks where a clocking hierarchy is established and the routers may need to pass clock through the network, additional considerations are needed.

On Cisco modular access routers with AIM voice cards installed, the controller shows "controlled slips" unless you add the **network-clock-participate** and **network-clock-select** commands.

On the Cisco 7200VXR platform, the **frame-clock-select** command is required for the voice cards. This command is particularly important for the Cisco 7200VXR voice gateways because, by default, the internal TDM bus is not driven by the local oscillator. Since the E1 trunks are normally synchronized to the telephony network, the result is hidden clocking errors and intermittent fax transmission problems. More detail is available in Cisco bug ID CSCdv10359 (registered customers only).

Checking Fax Interface Type

On some platforms, including the Cisco 3660, Cisco AS5300, Cisco AS5350, Cisco AS5400, and Cisco AS5800 platforms, the router defaults to fax interface-type modem. The **fax interface-type modem** global configuration command forces fax calls to a modem (usually for T.37 Store and Forward fax) and not to a DSP. For Cisco fax relay to work, the fax call must be sent to a DSP, which means it must be configured by the issuing of the **fax interface-type vfc** command.

```
Router(config)# fax interface-type ?
modem Use modem card
vfc   Use Voice Feature Card
```

Cisco_IOS_Voice_Troubleshooting_and_Monitoring_--_Fax_Relay

```
Router(config)# fax interface-type vfc
You must reload the router
```

Make sure you reload the router; otherwise the command does not take effect. Fax calls fail on the universal gateways listed above with Cisco fax relay (or T.38), so this is an important command to check.

The **fax interface-type vfc** command was not necessary in Cisco IOS software releases prior to Release 12.2. The problem is commonly seen when one of the voice gateways listed above is upgraded to Cisco IOS Release 12.2 or later.

Ensuring That the Fax Codec is Loaded During the Fax Call

Each fax machine displays the remote fax machine ID on its LCD screen at the completion of the fax negotiation phase. It is unlikely that the fax machines could complete negotiation if the fax codec has not been successfully downloaded. On the other hand if no remote fax machine ID is displayed, further debugging in this area is appropriate.

There are two ways to make sure that the voice gateways detect the fax transmission and successfully load the fax codec:

- Issue the **debug vtsp all** command and the **debug voip ccapi inout** call trace.
- Issue the **show voice trace** command. Show commands are less resource intensive on the router than debug commands and are preferable in production networks. Shown below is sample output from a **show voice trace** command on an ISDN interface:

```
BrisVG200gwy01# show voice trace 1/0:15
1/0:15 1
1/0:15 2
1/0:15 3
1/0:15 4
1/0:15 5
1/0:15 6
1/0:15 7
1/0:15 8
1/0:15 9
1/0:15 10 State Transitions: timestamp (state, event) -> ...
63513.792 (S_SETUP_REQUEST, E_TSP_PROCEEDING) ->
63515.264 (S_SETUP_REQ_PROC, E_TSP_ALERT) ->
63515.264 (S_SETUP_REQ_PROC, E_CC_BRIDGE) ->
63515.332 (S_SETUP_REQ_PROC, E_CC_CAPS_IND) ->
63515.332 (S_SETUP_REQ_PROC, E_CC_CAPS_ACK) ->
63515.348 (S_SETUP_REQ_PROC, E_CC_CAPS_IND) ->
63515.348 (S_SETUP_REQ_PROC, E_CC_CAPS_ACK) ->
63515.356 (S_SETUP_REQ_PROC, E_CC_CAPS_IND) ->
63515.356 (S_SETUP_REQ_PROC, E_CC_CAPS_ACK) ->
63518.656 (S_SETUP_REQ_PROC, E_CC_REQ_PACK_STAT) ->
63518.660 (S_SETUP_REQ_PROC, E_DSP_GET_VP_DELAY) ->
63518.660 (S_SETUP_REQ_PROC, E_DSP_GET_VP_ERROR) ->
63518.660 (S_SETUP_REQ_PROC, E_DSP_GET_RX) ->
63518.660 (S_SETUP_REQ_PROC, E_DSP_GET_TX) ->
63521.028 (S_SETUP_REQ_PROC, E_CC_REQ_PACK_STAT) ->
63521.028 (S_SETUP_REQ_PROC, E_DSP_GET_VP_DELAY) ->
63521.028 (S_SETUP_REQ_PROC, E_DSP_GET_VP_ERROR) ->
63521.028 (S_SETUP_REQ_PROC, E_DSP_GET_RX) ->
63521.028 (S_SETUP_REQ_PROC, E_DSP_GET_TX) ->
63524.128 (S_SETUP_REQ_PROC, E_TSP_CONNECT) ->
!--- Fax tone detected:
63529.352 (S_CONNECT, E_DSP_TONE_DETECT) ->
63529.356 (S_LFAX_WAIT_ACK, E_PH_CODEC_ACK) ->
```

!--- Fax codec being downloaded to DSPs:

Disabling Fax Relay and Change Codec for Pass-Through

In the previous troubleshooting steps you established that voice calls work, faxes work through PSTN, and all digital interfaces in the fax relay path are free from errors. The current step determines whether faxes can go through with fax relay disabled. For the VoIP/VoATM/VoFR dial peers, enter the following to disable the fax rate:

```
Router(config)# voice-port 2/0:15
Router(config-voiceport)# no echo-cancel enable
Router(config)# dial-p voice 3
Router(config-dial-peer)# fax rate disable
Router(config-dial-peer)# codec g711ulaw
Router(config-dial-peer)# no vad
```

Make sure these commands are entered on both gateways. These commands disable fax relay, disable echo cancellation, and force the call to use a high-bandwidth codec without VAD. The router then samples the tones as it would for a normal voice call, and with the high-bandwidth codec (G.711), the most precise sample possible is captured. The tone to be replayed on the other side is as accurate as possible. The caveat to this step is that since G.711 is a 64-kbps bandwidth codec, each call consumes up to 80 kbps (for VoIP) when additional transport protocol overhead is added.

If this test is positive, two things have been accomplished. First, if per-call bandwidth consumption is not a major issue for the network, there is now a potential fax pass-through workaround for the fax relay problem. Second, and more significantly, if bandwidth consumption is an issue, the problem has been isolated to the fax relay software and you should open a TAC case.

If this test fails, whatever is causing the fax calls to fail with fax relay is also probably causing the failures with this test. The problem might be that the network might have a large amount of jitter or packet loss.

Checking for Packet Loss on the Voice Network

Here is the easiest and most accurate way to determine if there is a packet loss:


1. Disable VAD on the VoIP dial peers.
2. Make a voice call between the same ports where the fax machines are connected. (Fax machines may be able to serve as ordinary phones or you might need to connect the handsets to the same ports where the fax machines are connected.)
3. When the call is connected, there are two main steps to take:
 1. Issue the **show voice dsp** command. You can see in the output that one of the DSP channels has the configured codec loaded. Usually the column "TX/RX-PAK CNT" shows that the transmit and receive packet counters are equal, meaning that no packets are being lost. If the counters are not equal, packets might be getting lost. Type the **show voice dsp** command several times at 30-second intervals to determine if the difference increases and packets are being lost.
 2. Issue the **show voice call summary** command to see which port (and timeslot if applicable) is allocated to the voice call. Type **terminal monitor** and issue the **show voice call** command with the voice port (and timeslot if applicable) to get the detailed DSP statistics. In the "****DSP VOICE VP_ERROR STATISTICS****" section of the output, look for the counters. They are usually 0 or below 20. If any of the counters have higher than 20, investigate the packet loss.

If the network appears to be lossy, it is not reasonable to expect fax relay to work reliably. It is possible to disable ECM, but further investigation is probably needed to ensure QoS is provisioned end-to-end so that the voice and fax relay traffic has priority and is never lost during the congestion.

Disabling Fax Relay ECM (Cisco Proprietary VoIP Only)

For networks with packet loss and lots of jitter, disabling ECM can improve fax relay calls. Issue the command **fax-relay ecm disable** to turn off ECM, so that a larger amount of jitter and packet loss can be tolerated.

Issuing the **fax-relay ecm disable** command improves fax relay performance in lossy networks, but this command is also recommended for basic troubleshooting. Even if there is not a noticeable jitter problem in the network, this command can sometimes help determine fax relay problems. This command is available under VoFR and VoATM dial peers but currently works only for VoIP.

 **Note:** This command also activates the packet loss concealment feature.

```
Router(config-dial-peer)# dial-peer voice 3
Router(config-dial-peer)# fax-relay ECM disable
```

Enabling T.38 Packet Redundancy (T.38 VoIP Only)

If T.38 for VoIP is being used as the fax relay protocol, you can turn on the T.38 packet redundancy feature by configuring the following command under the appropriate dial peers on both gateways:

```
Router(config-dial-peer)# fax protocol t38
  Ls-redundancy X Hs-redundancy Y
```

where $X > 0$ and $Y = 0$ (only make changes to Ls-redundancy)

If Cisco proprietary fax relay is in use, an alternative or additional option to disabling ECM is to change fax relay protocol to T.38 so that the T.38 packet redundancy feature can be tested. This feature might alleviate failure due to packet loss. However, T.38 packet redundancy significantly increases bandwidth usage, and it is preferable to eliminate the packet loss altogether, rather than alleviating the failures it causes.

Setting the Fax NSF Command to All Zeroes

The **fax nsf** command can be helpful for any fax machine that alters the NSF field during fax negotiation for proprietary encodings. This command allows the router doing fax relay to override the settings made by the fax machines trying to implement proprietary encodings. Before the **fax nsf** command was available, fax relay failed for such fax machines. Typically the **fax nsf** command is used to set the NSF field to all zeroes, forcing a standard fax negotiation from both sides. Using this command has been successful with certain brands of fax machines such as Harris and Lanier, and it is recommended when fax relay is failing.

```
Router(config-dial-peer)# fax NSF 000000
```

Achieving the Final Stages of Resolution

If the preceding troubleshooting steps do not resolve the fax relay issue, the problem might require more advanced troubleshooting. Listed below are additional steps to try before you open a case with the Cisco Technical Assistance Center (TAC).

- Learn the brands and models of the fax machines that are failing, and investigate those brands and models for known issues. Sometimes there are CARE cases or bugs that address problems for a certain brand of fax machine. For example, a search in the Bug Toolkit (registered customers only) for a Pitney Bowes fax shows a bug with Pitney Bowes fax machines and Cisco fax relay (CSCdu78373 (registered customers only)). This bug is not in the Cisco IOS software but is an incompatibility with the Pitney Bowes proprietary fax signaling protocol. A problem arises when the fax devices on each side of a connection are Pitney Bowes 9920s or 9930s. The workaround is to disable the proprietary protocol on the fax machines or to disable fax relay and use a higher bandwidth codec.
- Use search tools to look for known fax problems in the Cisco IOS software release where the problem is occurring. In the previous step, searches were made for a specific fax brand in the hope of identifying a known issue between a certain fax brand and the Cisco fax relay code. The next step is to perform a generic search, because there could be a fax relay bug in the Cisco IOS software release installed. For example, if fax relay using VoFR is not working in Cisco IOS Software Release 12.1(2)T, you can search for bugs using the Bug Toolkit on Cisco.com. In this example, you would use the following values:
 - ◆ Major version: 12.1
 - ◆ Revision: 2
 - ◆ Feature/component: VoFR
 - ◆ Keyword: fax

One of the bugs is Cisco bug ID CSCdr65984 (registered customers only), entitled "fax doesn't work for vofr." This bug causes all fax relays to fail for VoFR, and an upgrade is needed to a Cisco IOS software release in which this bug is no longer present.

- Eliminate hardware faults. In some cases it is easier to isolate the problem by excluding potential problem sources one by one. You can do this by replacing different hardware parts and using alternative IP connections between the gateways. When extra hardware is available, the following steps can help.
 - ◆ Use different ports on the routers-If your configuration involves two gateways connected to the PBXs or PSTN with E1 or T1 and if you have the FXS ports available, try to connect the fax machines directly to the FXS ports on the voice gateways. This procedure helps you further isolate the problem by excluding the possibility of the E1 cards failing, problems on the telephony side, and E1 synchronization or cable problems.
 - ◆ Try different hardware-If you have another voice gateway with FXS ports available, try to connect it directly with the Ethernet crossover cable to each of the voice gateways and send a fax using the fax machine connected to the FXS port. This procedure helps determine if there are problems in the VoX network involving queuing, fragmentation, or prioritization.
 - ◆ Use debug commands on the router to determine what is happening-See the following section for details about debug commands that are useful for troubleshooting fax relay problems.

Debugging Fax Relay


The following topics are associated with fax relay debugging:

- [T.30 Messages](#)
- [Fax Relay Debug Commands](#)
- [Fax Analyzers](#)

T.30 Messages

The debugs can be difficult to understand if you are not familiar with the messaging that occurs during a typical fax transmission. [Figure: T.30 Transactions](#) is a graphical representation of the basic T.30 transactions that occur for a single page fax transmission.

Figure: T.30 Transactions



Describing the details of these transactions is beyond the scope of this document, but listed below are definitions of the basic transactions that are seen during fax relay. The list is alphabetical for quick reference and includes messages that you are likely to see when you are debugging Cisco fax relay. For more in-depth information on this messaging or for information on messages that are not listed below, see the T.30 specification.

- **CED** (called terminal identification)-A 2100 Hz signal that is transmitted by the terminating fax device upon answering a fax call. This signal temporarily disables echo cancellers that are present on the connection to prepare the line for data transmission.
- **CFR** (confirmation to receive)-A response confirming that the previous messaging and training has been completed and that fax page transmission can begin.
- **CNG** (calling tone)-An 1100-Hz tone that is on for 0.5 seconds and then off for 3 seconds. This signal identifies the fax terminal as a nonspeech device. The signal also indicates that the initiating fax terminal is awaiting the DIS signal from the terminating fax terminal.
- **CRP** (command repeat)-A response that indicates that the previous command was received in error and needs to be repeated. (Optional)
- **CSI** (called subscriber identification) -Can be used to provide the specific identity of the called fax terminal through its international telephone number. (Optional)
- **DCN** (disconnect)-Ends the fax call and requires no response.
- **DIS** (digital identification signal) - Identifies the capabilities of the called fax terminal.

Cisco_IOS_Voice_Troubleshooting_and_Monitoring_--_Fax_Relay

- **DTC** (digital transmit command) -The response to the capabilities identified by the DIS signal. Here is where the calling fax terminal matches its capabilities with those provided in the called fax terminal's DIS message.
- **EOM** (end of message) - Indicates the end of a complete page of fax information.
- **EOP** (end of procedure)- Indicates the end of a complete page of fax information and signals that no further pages are to be sent. The other device can proceed to the disconnect phase of the fax call.
- **FTT** (failure to train) - Used to reject a training signal and request a retrain (retrains usually occur at lower modulation speeds).
- **MCF** (message confirmation) -Indicates that a message has been satisfactorily received.
- **MPS** (multipage signal)-Indicates the end of a complete page of fax information and signals that the receiver is ready for additional pages.
- **NSF** (nonstandard facilities)- Can be used to identify specific capabilities or requirements that are not covered by the T-series specifications. (Optional)
- **RTN** (retrain negative)- Indicates that a previous message has not been satisfactorily received. Retraining is needed to proceed (usually at a lower modulation speed).
- **RTP'** (retrain positive)- Indicates that a complete message has been received and that additional messages may follow after retraining.
- **TCF** (training check)- Sent through the higher-speed T.4 modulation system (versus the 300-kbps V.21 modulation used for the previous T.30 signaling) to verify training and indicate the acceptability of sending fax pages at this transmission rate.
- **TSI** (transmitting subscriber identification)- Identifies the transmitting (calling) fax terminal. (Optional)

Fax Relay Debug Commands

Useful fax relay debug commands include:

- **debug fax relay t30 all**
- **debug vtsp all**
- **debug vtsp vofr subframe 3**
- **Additional Debug Commands**

debug fax relay t30 all

The debug for Cisco fax relay is enabled with the **debug fax relay t30 all** command.

```
Router# debug fax relay t30 all
Debugging fax relay t30
```

Shown below is a copy of a debug from a failed fax relay session. This is a debug from the originating fax gateway running Cisco IOS Release 12.2(7a).

```
Router#
Dec 5 07:49:13.073: 1/2:62 1281347052 fr-entered (10ms)
Dec 5 07:49:17.985: 1/2:62 1281351950 fr-msg-det CRP
Dec 5 07:49:20.105: 1/2:62 1281354070 Fr-MSG-TX NSF
Dec 5 07:49:20.655: 1/2:62 1281354620 Fr-MSG-TX good crc,
 19 bytes
Dec 5 07:49:20.720: 1/2:62 1281354680 Fr-MSG-TX DIS
DEC 5 07:49:22.350: 1/2:62 1281356310 fr-msg-det TSI
DEC 5 07:49:23.045: 1/2:62 1281357000 fr-msg-det DCS
DEC 5 07:49:27.346: 1/2:62 1281361290 Fr-MSG-TX FTT
DEC 5 07:49:28.836: 1/2:62 1281362780 fr-msg-det TSI
DEC 5 07:49:29.531: 1/2:62 1281363470 fr-msg-det DCS
DEC 5 07:49:29.740: 1/2:62 1281363680 fr-msg-det bad crc,
 0 bytes
```

Figure: T.30 Transactions


Cisco_IOS_Voice_Troubleshooting_and_Monitoring_--_Fax_Relay

```
DEC 5 07:49:30.362: 1/2:62 1281364300 fr-msg-det bad crc,
 0 bytes
DEC 5 07:49:30.804: 1/2:62 1281364740 fr-msg-det bad crc,
 0 bytes
DEC 5 07:49:30.852: 1/2:62 1281364790 fr-msg-det bad crc,
 0 bytes
DEC 5 07:49:33.868: 1/2:62 1281367800 Fr-MSG-TX FTT
DEC 5 07:49:35.414: 1/2:62 1281369340 fr-msg-det TSI
DEC 5 07:49:36.113: 1/2:62 1281370040 fr-msg-det DCS
DEC 5 07:49:36.515: 1/2:62 1281370440 fr-msg-det bad crc,
 0 bytes
DEC 5 07:49:36.908: 1/2:62 1281370830 fr-msg-det bad crc,
 0 bytes
DEC 5 07:49:37.559: 1/2:62 1281371480 fr-msg-det bad crc,
 0 bytes
DEC 5 07:49:37.784: 1/2:62 1281371700 fr-msg-det bad crc,
 0 bytes
DEC 5 07:49:37.900: 1/2:62 1281371820 fr-msg-det bad crc,
 0 bytes
DEC 5 07:49:40.133: 1/2:62 1281374050 Fr-MSG-TX FTT
DEC 5 07:49:41.888: 1/2:62 1281375800 fr-msg-det TSI
DEC 5 07:49:42.583: 1/2:62 1281376490 fr-msg-det DCS
DEC 5 07:49:43.173: 1/2:62 1281377080 fr-msg-det bad crc,
 0 bytes
DEC 5 07:49:44.937: 1/2:62 1281378840 fr-msg-det bad crc,
 0 bytes
DEC 5 07:49:45.386: 1/2:62 1281379290 fr-msg-det bad crc,
 0 bytes
DEC 5 07:49:46.941: 1/2:62 1281380840 Fr-MSG-TX FTT
DEC 5 07:49:48.503: 1/2:62 1281382400 fr-msg-det DCN
DEC 5 07:49:50.631: 1/2:62 1281384520 fr-end-dcn
```

This debug shows the T.30 events that are taking place in the DSP during fax relay. Remember that the debugs are taking place from the perspective of the DSP interacting with the fax device. Any Fr-MSG-TX or transmit message is being transmitted from the DSP to the connected fax device. Any message that the DSP says that it detects (an fr-msg-det message, is a message that it received from the connected fax device.

Figure: DSP Message Flow illustrates the directional flow of the DSP messages when the **debug fax relay t30 all** command is issued.

Figure: DSP Message Flow



From the failed fax transaction shown in the debug above, you can see several badcyclic redundancy check (CRC) messages followed by a failure to train (FTT) message from the far side. From the debugs it looks like the problem involves the training signal. The bad crc errors and the FTT message returned from the other side indicate that the signal is corrupted or incompatible with the Cisco fax relay protocol. This debug is taken from a fax relay problem that occurs with a Lexmark Optra fax machine. The Lexmark is V.34-capable and attempts to connect at V.34 rates. V.34 is not supported in Cisco fax relay and the training errors shown here occur. See Cisco bug ID CSCdv89496 (registered customers only) for more details.

debug vtsp all

There are also other debug commands that might be useful for troubleshooting fax relay problems. These debugs might not be as easy to read or provide as much information as the T.30 debugs described above, but they can still be useful.

Voice Telephony Service Provider (VTSP) is an architecture for the interface between the Cisco IOS call control and a DSP endpoint connected to standard telephony equipment such as a PBX, fax, or central office via analog or digital interfaces.

For VoIP T.38 or fax relay, **debug vtsp all** can provide useful state information from the router. This debug command can be used to determine if the fax codec has been downloaded into the DSP.

debug vtsp vofr subframe 3

Another fax relay debug command that is helpful for fax using VoFR and VoATM is **debug vtsp vofr subframe 3**. This command outputs FRF.11 frames that have an Annex D fax relay payload type. There is a significant amount of output from this command even with just one fax relay call, and the hexadecimal must be decoded (the FRF.11 specification is helpful for hexadecimal decoding).

Additional Debug Commands

To debug T.38 capabilities exchange issues, use the **debug cch323 h245** command.

To debug DSP message exchanges between applications and the DSP, use the following debug commands:


- **debug voip ccapi inout**
- **debug hpi all** (on the Cisco 5300/2600/3600 and all other voice platforms using the TI c54x DSPs)
- **debug nextport vsmgr detail** (on the NextPort DSP platforms (Cisco 5400, 5850))

Fax Analyzers

Sometimes it is necessary to go beyond the debugging capabilities of the Cisco voice gateways to resolve fax relay problems. You can use tools such as protocol analyzers and fax analyzers to see what is occurring during fax relay operation. Fax analyzers such as the Genoa ChannelProbe/FaxProbe by QualityLogic or the HP Telegra can be positioned between the fax device and the Cisco gateway to capture what is occurring. Protocol analyzers such as Sniffer and Domino can be helpful when you need to view the fax relay packets that are being exchanged between the routers.

The ability to resolve a complex problem sometimes requires using a combination of equipment—an analyzer to capture the fax traffic at each fax machine and a protocol analyzer to capture the fax relay packets. A single fax call is placed to reproduce the problem, and then the information is captured from the attached devices for analysis. Figure: Test Equipment Placement shows where this test equipment is placed in the network.

Figure: Test Equipment Placement



Cisco_IOS_Voice_Troubleshooting_and_Monitoring_--_Fax_Relay

Most of the fax analyzers have adequate help screens and documentation. The T.30 specification is also very helpful. For the protocol analyzers, decoding can be a little more difficult because sometimes the encodings are proprietary or the analyzer software does not have the specific decode needed. For fax relay using VoFR and VoATM, Cisco gateways use standards-based Annex D from the FRF11 specification. If the protocol analyzer cannot decode the frame, the frame can be manually decoded through use of this specification. With fax relay and VoIP, a Cisco proprietary format is used for the fax relay packets.

With fax analyzer and protocol analyzer information, you should be able to resolve fax relay problems. Few fax relay problems reach this point, and when they do, escalation and DE resources should already be involved for further assistance.

For more information about troubleshooting fax relay, refer to the [Fax Relay Troubleshooting Guide, document 20227](#).