

## Full Video Warm Transfer with Queueing Not Working

<b>Problem Summary</b>	SIP trunk on outgoing call to VRU label is not getting routed to IVP.
<b>Error Message</b>	None
<b>Possible Cause</b>	Misconfiguration
<b>Recommended Action</b>	Set the SIP trunk on the route pattern for the ICME VRU label to point to IVP instead of CVP.
<b>Release</b>	Release 7.0(2)
<b>Associated CDETS #</b>	None.