

Full Video Warm Transfer with Queueing Not Working

Problem Summary	SIP trunk on outgoing call to VRU label is not getting routed to IVP.
Error Message	None
Possible Cause	Misconfiguration
Recommended Action	Set the SIP trunk on the route pattern for the ICME VRU label to point to IVP instead of CVP.
Release	Release 7.0(2)
Associated CDETS #	None.