

SIP Code 488 or 603 Returned on Full Video Call Rejection

Problem Summary	SIP code 488 or 603 is returned on a full video call rejection from IVP. A Fast Busy is heard.
Error Message	SIP code 488 or 603
Possible Cause	MCU or MVP/EMP unit on IVP is not registering or is in service.
Recommended Action	Follow the steps in the Radvision documentation to place the MCU or MVP in service.
Release	Release 7.0(2)
Associated CDETS #	None.