

## Enabling CME Tracing

<b>Problem Summary</b>	Any issue which requires CME tracing to be enabled.
<b>Error Message</b>	NA
<b>Possible Cause</b>	NA
<b>Recommended Action</b>	<p>1. Enable the traces by running the following command on the CME console.</p> <pre> service timestamps debug datetime msec service timestamps log datetime msec  logging buffered 1000000 logging rate-limit 10000 no logging console  sh ver sh run sh sip-ua  deb ccsip all deb voip ccapi inout deb voip vtsp all debug callmon info  sh deb </pre> <p>2. Perform all the tests.</p> <p>3. Turn off all the debugging by running.</p> <pre> u all </pre> <p>4. Get the contents of the log buffer using the following command.</p> <pre> sh logging </pre>
<b>Release</b>	Release 5.0(1) onwards
<b>Associated CDETS #</b>	The DDTS/CDETS should be visible on Bug Tool Kit. If it not visible, state "None." <b>Do not list internal bugs in this field.</b>