Enabling_CME_Tracing

Enabling CME Tracing

| Any issue which requires CME tracing to be enabled. |
|---|
| NA |
| NA |
| 1. Enable the traces by running the following command on the CME console. service timestamps debug datetime msec service timestamps log datetime msec logging buffered 1000000 logging rate-limit 10000 no logging console sh ver sh run sh sip-ua deb ccsip all deb voip ccapi inout deb voip vtsp all debug callmon info sh deb 2. Perform all the tests. 3. Turn off all the debugging by running. u all 4. Get the contents of the log buffer using the following command. |
| sh logging Release 5.0(1) onwards |
| The DDTS/CDETS should be visible on Bug Tool Kit. If it not visible, state "None." |
| Do not list internal bugs in this field. |
| |