

**H.323 client DTMF digits not detected**

<b>Problem Summary</b>	When a call originates from an H.323 client, DTMF digits are not collected.
<b>Error Message</b>	None.
<b>Possible Cause</b>	The H.323 client only produces in-band DTMF signals. Cisco Unified CM cannot detect in-band DTMF signals.
<b>Recommended Action</b>	None.
<b>Release</b>	Release 7.0(1)
<b>Associated CDETS #</b>	None.