

H.323 client DTMF digits not detected

Problem Summary	When a call originates from an H.323 client, DTMF digits are not collected.
Error Message	None.
Possible Cause	The H.323 client only produces in-band DTMF signals. Cisco Unified CM cannot detect in-band DTMF signals.
Recommended Action	None.
Release	Release 7.0(1)
Associated CDETS #	None.