

Second node removal or rebuild

Problem Summary	Node ID mismatch occurs when a node is removed from Unified CCX cluster. This mismatch also occurs when a rebuilt secondary node is added to the cluster.
Error Message	None.
Possible Cause	The problem can be caused if node ID is not removed during secondary node removal.
Recommended Action	It is advised to contact TAC to restore proper configuration on the setup.
Release	Release 7.0(X)
Associated CDETS #	None.