

## Trigger Configuration Error

<b>Problem Summary</b>	Unified CCX CM Telephony Subsystem is in partial service
<b>Error Message</b>	16037: Feb 18 12:09:24.168 IST %MIVR-SS_TEL-7-UNK:calculateSubsystemState -> subsystem partial in service,  cause: A number of route points are OOS; Some trigger has configuration error - RP[68923,68921,68922]
<b>Possible Cause</b>	The route point has a configuration error which leads to the Unified CCX CM Telephony Subsystem to be in partial service
<b>Recommended Action</b>	Fix the configuration error.
<b>Release</b>	Release 8.0(1) and Release 7.0(1)
<b>Associated CDETS #</b>	NA