

Trigger Configuration Error

Problem Summary	Unified CCX CM Telephony Subsystem is in partial service
Error Message	16037: Feb 18 12:09:24.168 IST %MIVR-SS_TEL-7-UNK:calculateSubsystemState -> subsystem partial in service, cause: A number of route points are OOS; Some trigger has configuration error - RP[68923,68921,68922]
Possible Cause	The route point has a configuration error which leads to the Unified CCX CM Telephony Subsystem to be in partial service
Recommended Action	Fix the configuration error.
Release	Release 8.0(1) and Release 7.0(1)
Associated CDETS #	NA