

Courtesy Callback Record Name Beep is not Heard

Problem Summary	When using the Courtesy Callback example Call Studio scripts, no beep is heard when the caller is prompted to record their name.
Error Message	None
Possible Cause	The gateway is not configured to use vxml 2.0
Recommended Action	<p>Add "vxml 2.0" and "vxml audioerror" to your gateway configuration:</p> <pre>vxml_gateway#config t Enter configuration commands, one per line. End with CNTL/Z. vxml_gateway(config)#vxml version 2.0 vxml_gateway(config)#vxml audioerror vxml_gateway(config)#^Z vxml_gateway#wr Building configuration... [OK]</pre>
Release	Release 8.0(1)
Associated CDETS #	None