Clicking Noise Heard During Scansoft TTS on IP Phones

Problem Summary	A clicking noise is heard during Scansoft TTS on IP phones.
Error Message	None.
Possible Cause	Change made to Scansoft OSSserver.cfg file under ScanSoft\SpeechWorks OpenSpeech Media Server\Server\config.
Recommended Action	Set the following: server.transport.audio.playerPacketDataSize VXIInteger 160
Release	Release 7.0(2)
Associated CDETS #	None.