To tell the master Subnet Manager to reset all port counters to zero, use the **reset port-counters** command.

reset port-counters

Syntax Description

This command has no arguments or keywords

Command Default

No default behavior or values.

Examples

The following example shows resetting all port counters on all switches:

```
fact> reset port-counters
Resetting port counters via Subnet Manager host01
```

Related Commands

scan fabric
scan fabric all
show counters monitored
show counters raw
show counters threshold