AAS - AAS cannot connect to SCCS

Problem Summary	AAS cannot connect to SCCS
Error Message	None
Possible Cause	None.
Recommended Action	Reinstall AAS and enter correct information. The recommended actions are: • Check for the site name in TAO Naming Viewer. This service can be run from D:\Nortel\TAO14\bin. The site name mentioned should be same as specified in the AAS registry AASSEISiteName. • Check for the nameserv.properties (used by naming service, located somewhere like D:\Nortel\vbrt51\properties or just search for that file). Check for the line naming service listening port. • The naming listener port should be same as in AAS registry AASSEINamingServicePort and SEI.properties file.SEI.properties file can be found at D:\Nortel\TAO14\properties. • Do not use the local IP address (127.0.0.1) as an AAS IP address. • Specify the site name in host file.
Release	Release 7.5(1) and 8.0
Associated CDETS #	None.