

IVR Subsystem Returns a 500 Rejection on VXML Fetch from Gateway

Problem Summary	IVR Subsystem returns a 500 rejection on VXML fetch from the gateway as seen in the gateway or CVP logs.
Error Message	500 Rejection
Possible Cause	Incorrect setting of parameter "Max Length of DNIS" on ICM service configuration page of Operations Console.
Recommended Action	Set parameter to the same length as the DNIS part of the label returned by ICM.
Release	Release 7.0(2)
Associated CDETS #	None.