

## SIP Code 488 or 603 Returned on Full Video Call Rejection

<b>Problem Summary</b>	SIP code 488 or 603 is returned on a full video call rejection from IVP. A Fast Busy is heard.
<b>Error Message</b>	SIP code 488 or 603
<b>Possible Cause</b>	MCU or MVP/EMP unit on IVP is not registering or is in service.
<b>Recommended Action</b>	Follow the steps in the Radvision documentation to place the MCU or MVP in service.
<b>Release</b>	Release 7.0(2)
<b>Associated CDETS #</b>	None.