

Trigger partition change causes JTAPI subsystem to go to Partial Service

Problem Summary	Changing of the partition of the Trigger/route point from Unified Communications Manager Administration causes Unified CCX CM Telephony subsystem to go to Partial Service
Error Message	Unified CCX CM Telephony subsystem goes to Partial Service
Possible Cause	Change of partition of route point/trigger
Recommended Action	This is caused by the below mentioned bug. The work around is to restart the Unified CCX Engine.
Release	Release 8.0(1) and Release 7.0(1)
Associated CDETS #	<u>CSCtb04305</u>