

Excessive Unavailable ASR Errors in VXML Server Log

Problem Summary	Excessive unavailable ASR errors in VXML Server application error log.
Error Message	SERVER ERROR:A VXML exception occurred:error.com.Cisco.media.resource.unavailable.asr
Possible Cause	The default MRCP timeout value of 3 seconds needs to be increased.
Recommended Action	The default MRCP timeout values need to be increased to 5 seconds on the gateway as follows: mrcp client timeout connect 5mrcp client timeout message 5
Release	Release 7.0(2)
Associated CDETS #	None.