

RTSP live monitoring sessions fail when using CUBE

Problem Summary	When using a mixed load in a CUBE deployment, multiple RTSP live monitoring sessions failed (RTSP packets were dropped). Recordings may also sound very choppy on playback.
Error Message	None.
Possible Cause	CUBE may be using a lower Ethernet cable connection (for example, 100 MB connection) instead of the suggested 1 GB Ethernet cable connection. Under a heavy load, this connection may cause multiple IP packets to drop.
Recommended Action	If your CUBE deployment is running heavy loads, verify that the Ethernet cable connecting CUBE to the switch is 1 GB.
Release	Release 8.5(3), Release 8.5(4), Release 9.0(1).
Associated CDETS #	None.