

If Switch Version Fails on Unified CCX, Reboot the Server

Problem Summary	Switch version (to higher or lower version) fails on a HA/SA Unified CCX setup.
Error Message	<i>Sync after switch version failed</i>
Possible Cause	The Unified CCX switch version can fail for many reasons, including network failure, DB service down, and so on when performing switch version on a node.
Recommended Action	Reboot the Unified CCX server because many services may not run after a switch version failure.
Release	All Unified CCX versions later than Release 8.0(1)
Associated CDETS #	None