

MCP server is unable to keep up with incoming recordings

Problem Summary	The Unified MCP server is unable to keep up with the number of recordings it's supposed to capture.
Error Message	None.
Possible Cause	By default, if the battery backup is not present or not operational, the write cache is disabled on the RAID controllers in the C-Series. When the write cache is disabled, write throughput is lowered.
Recommended Action	The RAID controllers in the C-Series have an optional battery backup for the write cache. Add the battery backup cache to achieve better performance.
Release	Release 8.5(1)
Associated CDETS #	None.