

## Error Code 31, 32, 33 Returned to ICM Script

<b>Problem Summary</b>	CALL_RESULT returns an error code 31, 32, or 33 to the ICM script.
<b>Error Message</b>	Error code 31, 32, or 33 received.
<b>Possible Cause</b>	If using ASR/TTS, the gateway is unable to connect to the ASR or the TTS server.
<b>Recommended Action</b>	To resolve this issue, the connection to the server must be restored.
<b>Release</b>	Release 7.0(2)
<b>Associated CDETS #</b>	None.